

---

**From:** Leonard C Pope (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=LEONA5286E]  
**Sent:** 4/27/2015 6:54:07 PM  
**To:** Michael A Glagola (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Mic0210]; Bob Jackson (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Robe218]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeff136]; Donald Fines (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Donal16]  
**CC:** Leonard C Pope (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=LEONA5286e]  
**Subject:** E Pond Ash Removal

No safety and no environmental issues other than the water leaking through what appears to be a seam in the concrete in E Spillway discharge . Glover started receiving trucks this morning stockpiling stone for the hall road from E pond to D pond around 54 loads today, E pond dewatering pump is up and running again pumping to D pond , Glover is installing a pump in the E pond outfall basin to pump the water back into E pond until the leak can be stopped.

Bruce Howard moving mats out of E Pond and placing around A/B/C ponds.

Fishburn has worked around D pond today.

GAI continuing to direct Bruce Howard and Fishburn.

Crofton arrived on site today looked at water leaks on C pond spillway and E pond spillway with Ruben Williams Supt for Glover and will get back with Ruben on repair and price for E spillway leak.

DOM Carter Cole has been on site with Crofton today.

Leonard "Whitey" C Pope

Dominion Lead

possum point

Cell PH 804-854-3359

[Leonard.C.Pope@Dom.Com](mailto:Leonard.C.Pope@Dom.Com)